
NPTEL » Electrical Machines (IITD)



About the Course Ask a Question Announcements Progress Mentor **Assignment 4** The due date for submitting this assignment has passed. Due on 2019-08-28, 23:59 IST. As per our records you have not submitted this assignment. For Question 1 and 2 Test data on a single-phase transformer with the secondary terminals short circuited is given below. Applied voltage: 60 V, current: 100 A, power input: 1.2 KW. Calculate (from the primary side) effective (equivalent) resistance in Ω No, the answer is incorrect. Score: 0 Accepted Answers: (Type: Range) 0.11,0.13 1 point Calculate (from the primary side) leakage reactance in Ω. No, the answer is incorrect. Score: 0 Accepted Answers: (Type: Range) 0.56,0.62 1 point For Question 3 and 4 A 50 Hz single-phase transformer has a turns ratio of 6. The resistances and reactances are 0.90 Ω and 1.5 Ω for HV winding and 0.13 Ω and 0.1855 Ω for low voltage winding respectively. Calculate the voltage to be applied to the high voltage side to obtain full load current of 200 A in the low voltage winding on short circuit. No, the answer is incorrect. Score: 0 Accepted Answers: (Type: Range) 229,332 Calculate the power factor on short circuit. No, the answer is incorrect. Score: 0 Accepted Answers: (Type: Range) 0.54,0.58 For question 5 to 8

The test results of a single-phase, 4 KVA, 200/400 V, 50 Hz transformer are given below. Open circuit: 200 V, 0.7 A, 70 W on low voltage (primary) side. Short circuit: 15 V, 10 A, 80W on high voltage (secondary) side. The equivalent circuit is given below. Calculate the value of R₀ in Ω No, the answer is incorrect. Score: 0 Accepted Answers: (Type: Range) 570,572 Calculate the value of X₀ in Ω No, the answer is incorrect. Score: 0 Accepted Answers: (Type: Range) 329,333 Calculate the value of R_t in Ω No, the answer is incorrect. Score: 0 Accepted Answers: (Type: Range) 0.18,0.22 8) Calculate the value of X_t in Ω No, the answer is incorrect. Score: 0 Accepted Answers: (Type: Range) 0.3,0.33 For Question 9 and 10 power factor. Calculate the iron loss in kW No, the answer is incorrect. Score: 0 Accepted Answers: (Type: Range) 0.98,1.06 Calculate the full load copper loss in kW No, the answer is incorrect. Score: 0 Accepted Answers: (Type: Range) 2.9,3.1

The efficiency of a 400 KVA, single-phase transformer is 98.77% when delivering full load at 0.8 power factor and 99.13% at half load and unity kW. Calculate the all-day efficiency (in %) of the transformer. No, the answer is incorrect. Score: 0 Accepted Answers: (Type: Range) 95,96 For Questions 12 to 14 when supplying half of full load current at unity power factor. 12) Find the iron loss in watts No, the answer is incorrect. Score: 0 Accepted Answers: (Type: Range) 264,270 Find the copper losses (in watts) corresponding to full load current. No, the answer is incorrect. Score: 0 Accepted Answers: (Type: Range) 945,955 Calculate the load current (in A) at maximum efficiency. No, the answer is incorrect. Score: 0 Accepted Answers: (Type: Range) 4.5,5 15) A 40 KVA transformer has got a maximum efficiency of 97 % at 80% of rated load at UPF. During a full day it is loaded as follows: 9 hrs - 6 KW - 0.6 lag(pf) 8 hrs - 25 KW - 0.8 lag 7 hrs - 30 KW - 0.9 lag Calculate its all-day efficiency. No, the answer is incorrect. Score: 0 Accepted Answers: (Type: Range) 95.5,96.8 For Question 16 and 17 A 500/250V, 5 kVA two-winding transformer is to be used as an auto transformer to supply a 500 V circuit from a 750 V source at 50 Hz (as shown below). When tested as a two-winding transformer at rated load, it yielded an efficiency of 96% at 0.8 PF lagging. 500 V/250 V Input N₁ Output Determine its kVA rating as an auto-transformer. No, the answer is incorrect. Score: 0 Accepted Answers: (Type: Range) 14.99,15.01 17) Find its efficiency at full load at 0.8 PF lagging as an auto-transformer. No, the answer is incorrect. Score: 0 Accepted Answers:

1 point 11) 16A, 200 kVA single phase transformer is in circuit throughout 24 hours. For 8 hrs in a day, the load is 150 kW at 0.8 power factor lagging and for 7 hours, the load is 90kW at 0.9 power factor. Remaining time or the rest period is at no load condition. Full load copper loss is 4 kW and the iron loss is 1.8 1 point A 100 kVA, 50 Hz, 440/11000 V, single phase transformer has an efficiency of 98.5% when supplying full load current at 0.8pf and an efficiency of 99% 1 point 1 point 0 points 1 point 1 point (Type: Range) 98,99 1 point